ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
8

Ward Name
Kodigehalli

Street ID
W0169, W0134, W0165, W0171, W0161

Street Name
NA, 1st Crs

Significant Landmark
Defence Colony Shakaranagar 1st ,2nd 3rd Cross roa

Segment No.
8/C-W0169/S110616

Total Length (m)
534.69

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	143.42	77.583775	13.058981	77.585091	13.059104	W0183	W0165
2	108.80	77.584805	13.059118	77.584900	13.060097	W0161	W0134
3	131.37	77.584514	13.059104	77.584599	13.060288	W0161	W0134
4	151.10	77.584182	13.059074	77.584303	13.060435	W0161	W0134

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to Roads and Drain at Defence Colony Shakaranagar 1st ,2nd 3rd Cross road and Raghavendraswamy Temple Road in ward no 8 Kodigehalli Sub-

Sanctioned Estimated Amount (Rs.)
2000000

Sanctioned Year
2014

Year
2014 - 2015

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to Roads and Drain at Defence Colony Shakaranagar 1st ,2nd 3rd Cross road and Raghavendraswamy Temple Road in ward no 8 Kodigehalli Sub-Division Yelahanka zone

Job No. / Work Code
008-15-000020

Work Order No.
EE/BTP/BBMP/E-PMT/WO /247/2014-15

Work Order Date
28/01/2015

Period of Extention
60 DAYS

Defect Liability Period From
28/01/2015

Defect Liability Period To
27/01/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
MADHUSUDHAN .R		0.00
Phone No.	**E-Mail ID**	
9740402579		

Field Inspection Details

Number of Trees	Any Other Information	Name
10		SRINIVASA MURTHY
Date of Inspection	**Remarks**	
10/11/2016	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0169, W0134, W0165, W0171,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	11/11/2016	10/12/2016	COMPLETED
SE	VASU K M	11/11/2016	10/12/2016	COMPLETED
EE	RAJANIKANTH MALLI	11/11/2016	10/12/2016	COMPLETED
AEE	RAJANIKANTH MALLI	10/11/2016	10/12/2016	COMPLETED
AE	SRINIVASA MURTHY	10/11/2016	10/12/2016	COMPLETED
AE	SRINIVASA MURTHY	10/11/2016	10/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0169, W0134, W0165, W0171,